


# SideWinder New Style Capstan Replacement for P/N 36579

**Remove older capstan (with 16in inner hub)  
from the GMP Sidewinder**



**Install updated replacement capstan  
onto the SideWinder**

